

Ford Swather



Description	EPP	OEM	S/N note	Part Notes
4400				
Compressor	2 CO-2054CA	54358		Sanden new with clutch, SD508, #8387 152mm / 6.00 dia, 2A grv, 12 volt, Vert flare fittings, B head, Ear mount
Clutch	600-393	33366		Sanden new 6.00 dia, 2 grv (use with SD508/SD510)
4700				
Compressor	2 CO-9125	88340		Sanden new with clutch, SD510, #9125 132mm / 5.25 dia, 2 grv, 12 volt, Horizontal tube-o fittings, M head 5-bolt, Ear mount
Clutch	600-729	55302		Sanden new 5.22 dia, 2 grv
Expansion Valve	904-304	70267		Oring Inlet 3/8 M, Outlet 1/2 M, 12" capillary 3/8" coil, 2 ton, ext. equalizer 13" x 1/4FO
Receiver Dryer	804-1830	48510		3.00 x 9.75, male oring Inlet 3/8 MO x Outlet 3/8 MO
4750				
Compressor	2 CO-9125	88340		Sanden new with clutch, SD510, #9125 132mm / 5.25 dia, 2 grv, 12 volt, Horizontal tube-o fittings, M head 5-bolt, Ear mount
Clutch	600-729	55302		Sanden new 5.22 dia, 2 grv
Expansion Valve	904-304	70267		Oring Inlet 3/8 M, Outlet 1/2 M, 12" capillary 3/8" coil, 2 ton, ext. equalizer 13" x 1/4FO
Receiver Dryer	804-1830	48510		3.00 x 9.75, male oring Inlet 3/8 MO x Outlet 3/8 MO
9030				
Compressor	2 CO-9125	9704118		Sanden new with clutch, SD510, #9125 132mm / 5.25 dia, 2 grv, 12 volt, Horizontal tube-o fittings, M head 5-bolt, Ear mount
Clutch	600-729	55302		Sanden new 5.22 dia, 2 grv
Expansion Valve	904-304	70267		Oring Inlet 3/8 M, Outlet 1/2 M, 12" capillary 3/8" coil, 2 ton, ext. equalizer 13" x 1/4FO
Receiver Dryer	804-1830	48510		3.00 x 9.75, male oring Inlet 3/8 MO x Outlet 3/8 MO

1: Check illustrations
2: May require oil change
3: New, check illustration